

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>11/04/2025</u> Submitted Date: <u>11/04/2025</u> Document Number: <u>719000883</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID: 326148    Inspector Name: GARCIA, CHARLES    On-Site Inspection:    
 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON    State: TX    Zip: 77208

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	<a href="#">SJB inspect</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215948	WELL	PR	01/01/2003	CBM	067-07554	HUBER-HECHT 1-4	PR
455099	GAS COMPRESSOR STATION	AC	05/23/2018		-	HUBER HECHT 1-4 - CDP	AC

**General Comment:**

[Inspection Report Summary](#)  
 On 11/4/25 | Inspector Charles Garcia conducted an on-site inspection.  
 Location: HUBER-HECHIT 1-4  
 API# 067-07554  
 Operator: HILLCORP ENERGY COMPANY  
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK PLACARD SUN DAMAGED AND NOT LEIBLE SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	11/11/2025
Emergency Contact Number:			
Comment:	24 Hr #970-247-6916 Emergency #911		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	PRODUCED WATER TANK HOG WIRE		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS SOUND WALLS		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Other # 1			corrective date
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Pump Jack # 1			
Comment:			
Corrective Action:		Date:	
Type: Prime Mover # 1			
Comment:	GAS		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.245600,-107.756600
Comment:	21 PRODUCED WATER TANK HAS VERY LITTLE PAINT ON TOP OF TANK STARTING TO RUST SEE LOCATION PICTURES				
Corrective Action:	600.b MAINTAIN TANK PAINT				Date: 01/04/2026

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404423564	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317368">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317368</a>
719000884	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317357">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317357</a>