

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2025

Submitted Date:

11/05/2025

Document Number:

711902763

FIELD INSPECTION FORM

Loc ID 317125 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10690
 Name of Operator: IMPETRO RESOURCES LLC
 Address: 558 CASTLE PINES PKWY UNIT B-4
 City: CASTLE PINES State: CO Zip: 80108

Findings:

9 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Bongers, Brent	361-935-5633	bbongers@impetroresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236572	WELL	PR	08/01/2025	OW	121-09062	WILSON 1	PR

General Comment:

ROUTINE FIR - THIS FIR IS SUBMITTED LATE DUE TO TECHNICAL DIFFICULTIES PROCESSING REPORTS. CA'S ARE CALCULATED FROM THE DAY OF INSPECTION. PLEASE READ FIR COMPLETELY FOR CA'S AND COMMENTS SEE PHOTOGRAPHS ATTACHED

Location			
Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	PROVIDE SIGN WITH INFORMATION PER RULE 600 SERIES F.I. SCHURE SPOKE TO PUMPER ON LOCATION STATING SIGNAGE WAS ON ORDER.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	PROVIDE SIGNAGE PER RULE 600 SERIES OPERATOR REP. STATED NEW SIGNS ON ORDER		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	PROVIDE SIGNAGE PER RULE 600 SERIES F.I. SCHURE SPOKE TO PUMPER ON LOCATION STATED NEW SIGNAGE WAS ON ORDER.		
Corrective Action:			Date:
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	REMOVE TUBING FROM GROUND @ PJ		
Corrective Action:	COMPLY WITH RULE 606		Date: 11/27/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	NONE		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	NO CHANGE IN EQUIPMENT INVENTORIED		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 236572 Type: WELL API Number: 121-09062 Status: PR Insp. Status: PR

Producing Well

Comment: OW

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404425308	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319750
711902772	PHOTOGRAPHS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319749