

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/30/2025</u> Submitted Date: <u>11/12/2025</u> Document Number: <u>718300101</u>
FIELD INSPECTION FORM			

Loc ID 487521 Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Kari		Kari.l.brown@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487521	LOCATION	AC			-	DECHANT OZBUN T2N-R64W-S19 L01 Loc	EI
487522	TANK BATTERY	AC	08/07/2024		-	DECHANT OZBUN T2N-R64W-S19 L01 TB	EI
491917	SPILL OR RELEASE	AC	10/23/2025		-	Dechant Ozbun T2N-R64W-S19 L01	EI

General Comment:

This is an ECMC Environmental Field Inspection to determine progress on Spill ID 491917 and Remediation Project #38679. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

DECHANT OZBUN T2N-R64W-S19 L01 Loc (Location ID 487521)
 DECHANT OZBUN T2N-R64W-S19 L01 TB (Facility ID 487522)
 Spill Name: Dechant Ozbun T2N-R64W-S19 L01
 Spill ID: 491917
 Spill Details: On 10/15/2025, the potential presence of impacted material(s) was identified via hydrocarbon odor and hydrocarbon staining during the decommissioning activities at the Dechant Ozbun T2N-R64W-S19 L01, tank battery, sample: PWV01-B, PWV01-N, PWV01-S, PWV01-E and PWV01-W located at the produced water vessel in the same excavation. The volume of potentially impacted material(s) is not currently known. Initial soil sampling is underway to determine whether any constituents are present at levels in excess of Table 915-1 standards. Groundwater was not encountered during decommissioning activities. Final analytical results will be included as part of the supplemental Form 19 submission.
 Reported Date of Discovery: 10/15/2025
 Remediation Project #38679
 Last Form 27 Received: 4/15/2025

Current site status:

- The excavation associated with removal of and sampling at the produced water vessel and visible in photo documentation attached to Form 19i Doc #404395445 and associated with Spill ID 491917 was not observed during ECMC's inspection and appears to have been backfilled to grade.
- The tank battery has been decommissioned; 3rd party meter shed remains on location
- Weeds and debris were observed around the perimeter of the location

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: WEEDS

Comment:

Corrective Action:

Date: 11/26/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 487521 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487522 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491917 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Form 19i/s Doc #404395445 was submitted to report the potential presence of impacted material(s) identified on 10/15/2025 via hydrocarbon odor and hydrocarbon staining during the decommissioning activities at the Dechant Ozbun T2N-R64W-S19 L01, tank battery, samples: PWV01-B, PWV01-N, PWV01-S, PWV01-E and PWV01-W located at the produced water vessel in the same excavation. The historic release has been assigned Spill ID 491917.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Form 19 Supplemental requesting closure is due by January 13, 2026. Date: 01/13/2026

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	The excavation associated with removal of and sampling at the produced water vessel and visible in photo documentation attached to Form 19i Doc #404395445 and associated with Spill ID 491917 was not observed during ECMC's inspection and appears to have been backfilled to grade.			
Corrective Action	Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal. Additionally, Operator shall provide all tickets for material hauled on site for backfill. This documentation shall be included on the subsequent Supplemental Form 19.			Date: 01/13/2026

Spill/Remediation:

Comment: Remediation Project #38679 was created for decommissioning of the DECHANT OZBUN T2N-R64W-S19 L01 Loc (Location ID 487521). Operator shall return to Quarterly reporting for REM 38679.

Corrective Action: Submit a Supplemental Form 27 to include an updated implementation schedule in addition to proposed specific actions to address the identified release. Note: Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance of any schedule changes. Form 27s Doc #404140371 listed 05/04/2026 as the proposed Date of Initial Actions described in Site Investigation Plan (start date). Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Date of Inspection: 10/30/2025 Weather: Clear, slight breeze <5mph, 50°F PPE: Level D & FR Clothing	andersoln	11/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718300102	2025_1030_Dechant Ozbun TB Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7327358