

Inspection Photos

11/10/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335271

Inspection Doc: 719200416

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 3: Photos showing stormwater controls on the northeastern portion of the location have been replaced or maintained. The Corrective Action from inspection #719200201 has been resolved.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 4: Photos showing stormwater controls (sediment traps and culverts) throughout the location have been maintained. The Corrective Actions from inspection #719200201 has been resolved.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 5: Photos showing stormwater controls (sediment traps and culverts) throughout the location have been maintained. The Corrective Actions from inspection #719200201 has been resolved.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 6: Photos showing the northeastern interim area. The area appears to have been recently decompacted; however, the area does not appear to have been cross-rippled to a depth of 18 inches and reseeding efforts are not apparent. Additionally, a Resolution has not been submitted summarizing work performed. A follow-up inspection will be conducted in future growing seasons to determine progression towards 1003 reclamation requirements.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



Photo 7: Photo showing a sediment trap on the eastern end of the location is laden with sediment, reducing capacity. Comply with 1002.f. and maintain stormwater BMPs.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources