

Inspection Photos

11/07/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 335577

Inspection Doc: 718100962

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show degradation to the working pad surface, including vehicle tracking. Stormwater appears to be ponding on the Location resulting in degradation and destabilization. BMPs to allow for controlled and proper management of stormwater runoff, as well as stabilization and tracking control measures are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 3: Photos show vehicle tracking/degradation on the working pad surface. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 4: Photos taken from the separator equipment on the Location. See comments under photo 1. Photos also show evidence of ponding and comingling of stormwater with production equipment on the Location.



Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 5: Photos taken from the east end of the Location. Photo shows point where stormwater runoff is discharging from the Location. No engineered outlet or other BMPs to allow for proper and controlled stormwater discharge observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 6: Photo taken from the access road facing north. Photo shows erosion degradation due to runoff. Runoff from these areas discharge to the CHEVRON-66S96W/4SWNW location immediately south, and is contributing to stormwater issues observed there. Refer to inspection #718100960 for additional details.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: QB ENERGY OPERATING LLC #10844
Location ID: 335577



Photo 7: Photo shows tank battery facility on the south end of the Location.



Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335577



Photo 8: Photos taken from the south of the well, facing north. Photo shows unmarked anchor on Location. Operator appears to have only marked anchors along the west end of the Location. Unsure if anchors along the east end of the Location have been removed, or have been buried. Anchors require marking pursuant to Rules 1003.a and 603.j. If anchors on the Location are no longer necessary, they are considered unused equipment and should be removed pursuant to Rule 606.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources