

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2025

Submitted Date:

11/10/2025

Document Number:

720800134

**FIELD INSPECTION FORM**

Loc ID 422413 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422377	WELL	SI	06/01/2024	OW	123-33238	CASTOR LC 27-72HN	SI

**General Comment:**

[This is a Compliance Field Audit of the Scout Card, Related Documents and the Location for an abandoned well on an active Location](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused Pipe, Day Tanks and Secondary Containments, Automation Equipment remain on Location. * Well appears to have been Plugged and Abandoned, 3 months to remove all surface Equipment has pasted.		
Corrective Action:	Comply with Rule 1004	Date:	12/01/2025

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type LOCATION

Comment: Barbed Wire

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Equipment:**

Type: Gas Meter Run	# 2		corrective date
Comment:	Sales and Buy-Back Meters		
Corrective Action:		Date:	

**Venting:**

Yes/No

Comment:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 422377 Type: WELL API Number: 123-33238 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Appears to have been Plugged and Abandoned per Form 6S (IN PROCESS) 404217130 dated 05.26.2025 with a Surface Plug Date of 04.01.2025 and a Cut and Cap Date of 04.28.2025  
Lastest Quaterly Form 27 - 404375536 dated 10.20.2025

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720800135	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328380">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328380</a>