

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

11/06/2025

Document Number:

709100584

FIELD INSPECTION FORM

Loc ID 330643 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10773
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC
Address: 5251 DTC PKWY STE 950
City: GREENWOOD State: CO Zip: 80111

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	Regulatory
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251597	WELL	SI	02/01/2019	OW	123-19400	BRENNAN 1	SI

General Comment:

On October 22, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the Brennan-610N58W/32NWNW location (Location ID 330643) along with the wells on location.

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Signage contains inaccurate information at oil and gas location. Signage contains "Whiting Oil & Gas Inc".		
Corrective Action:	Install or update sign to comply with Rule 605.a.	Date:	12/22/2025

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type			
Comment:	Windssock inadequate / Repair or replace windsock		
Corrective Action:		Date:	
Type			
Comment:	Trash observed on location		
Corrective Action:	Comply with Rule 606	Date:	11/12/2025
Type			
Comment:	Burrowing observed around the Brennan 1 wellhead (API 123-19400)		
Corrective Action:	Repair burrowing surrounding the wellhead	Date:	11/20/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 251597 Type: WELL API Number: 123-19400 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404426952	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321358
709100585	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321340