

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

11/06/2025

Document Number:

709100586

**FIELD INSPECTION FORM**

Loc ID 433936 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

3 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		nbl_djbu_inspections@nblenergy.com	ALL INSPECTIONS ONLY
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445198	WELL	PR	02/01/2025	OW	123-42943	Ringo Federal LC23-720	PR
445202	WELL	PR	02/01/2025	OW	123-42947	Ringo Federal LC23-725	PR

**General Comment:**

On October 22, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the LC 11-16/Multi location (Location ID 433936) along with the wells on location.

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

Type			
Comment:	Signage present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type			
Comment:	Trash and unused equipment observed on location		
Corrective Action:	Comply with Rule 606	Date:	11/12/2025

Overall Good:

**Spills:**

Type	Area	Volume			
Comment:	Hydrocarbon staining present on tank battery fill material, valve connected to buried tank (See photo 13), and underneath compressor skid plate (see photo 26).				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:	11/22/2025

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date	
Comment:	Wildlife protection inadequately installed on valve connected to 7 bbl pit (see photo 24)			
Corrective Action:	Comply with Rule 902.b to install or repair wildlife protection equipment.		Date:	11/14/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 445198 Type: WELL API Number: 123-42943 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445202 Type: WELL API Number: 123-42947 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404426956	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321361</a>
709100587	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321350">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321350</a>