

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/06/2025

Document Number:

718300099

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
5 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 100322  
 Name of Operator: NOBLE ENERGY INC  
 Address: 1099 18TH STREET SUITE 1500  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Rollins, Grace		grace.rollins@state.co.us	
, Environmental		rbuef27@chevron.com	
Peterson, Dan		danpeterson@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420281	LOCATION	AC			-	ARISTOCRAT PC H 11-19D	EI
484292	TANK BATTERY	AC	04/18/2023		-	Aristocrat PC H 11-19D Tank Battery	EI
491220	SPILL OR RELEASE	AC			-	Aristocrat PC H11-19D	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 491220 and Remediation Project # 37375. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: Aristocrat PC H11-19D

Spill ID: 491220

Remediation Project #: 37375

Facility ID: 484292

Location ID: 420281

Reported Date of Discovery: 08/20/2025

Date of Inspection: 10/30/2025

Weather: Clear, slight breeze <5mph, 50°F

Previous FIR: 8/25/2025 Doc #717100361

Spill is located within or adjacent to:

- Freshwater Emergent Wetlands (within) and Riverine Wetlands (~245 ft west)
- Bald Eagle Roost Site High Priority Habitat and Mule Deer Severe Winter Range High Priority Habitat (within)
- Surface water (agricultural pond ~130 ft southwest; Gilmore Ditch, ~270 ft west)

Current site status:

- Signage with emergency contact number has fell on location.
- The tank battery has been decommissioned.
- The excavation at the release location remains backfilled to a grade above that of the surrounding location.
- Areas of soil with gray/brown staining are visible on the surface at the backfilled excavation at the approximate release location.
- A water pump was observed at the agricultural pond southwest of the release location.
- The work-over rig visible at the adjacent Aristocrat 11-21 well (API # 05-123-15805) during the previous inspection (Doc #717100361) is gone.
- No remedial excavation appears to have occurred since the previous inspection.

See attached corrective actions.

ECMC Enforcement is copied on this inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 420281 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484292 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491220 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project # 37375 was created for decommissioning of the ARISTOCRAT PC H 11-19D Tank Battery. Spill ID 491220 was created to address the remediation of impacts identified at the produced water vessel of the tank battery. The tank battery has been decommissioned. Areas of soil with gray and brown staining are visible on the surface at the backfilled excavation at the approximate release location.

Corrective Action: This spill/release report will remain unresolved until a Supplemental Form 27 is approved under the existing Remediation Project #37375. The Supplemental Form 27 shall include an updated implementation schedule in addition to proposed specific actions to address the identified release. Form 27s Doc #404338521 has been received and is currently in review.

Date: \_\_\_\_\_

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: 5

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	Operator has indicated that zero waste has been removed from this location during facility decommissioning and removal of the partially buried concrete produced water vessels; therefore, no waste manifests have been generated.			
Corrective Action	Per ECMC Rule 905.a.(1) Operators will ensure that E&P Waste is properly stored, handled, transported, treated, recycled, or disposed to prevent threatened or actual adverse environmental impacts to air, water, soil, or biological resources, or to the extent necessary to ensure compliance with the concentration levels in Table 915-1, radiation control standards, and WQCC Regulation 41 numeric and narrative Groundwater quality standards and classifications, as incorporated by reference in Rule 901.b. CA due date back-dated to date of discovery.  Operator will provide notice via email to the ECMC Area EPS at least 48 hours prior to excavation, backfill, monitoring well installation, or any sampling events performed on location. Email notification must include the scope of work, start date and time, and contact information for the on site contact.			Date: 08/20/2025

**Spill/Remediation:**

Comment: The excavation at the release location has been backfilled to a grade above that of the surrounding location. Areas of soil with gray and brown staining are visible on the surface of the backfilled excavation at the approximate spill location.

Corrective Action: Per Rule 912.a.(2): Operator's will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Per Rule 913.d.(1): Operators will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. CA due date back-dated to date of discovery.

Date: 08/20/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404426794	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321215</a>
718300100	2025_1030_Aristocrat PC H11-19D Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7321214</a>