

Final Reclamation and Stormwater Inspection

November 5, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 306078

Well Name: SEVCIK V #27-23

Inspection Document #: 718601162

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SEVCIK V #27-23
Location ID: 306078



Photo 1. Looking northwest down the former access road. Some undesirable weeds such as russian thistle are present on the access road. Desirable vegetation that is reflective of the surrounding reference area is present on the access road.



Photo 2. Looking north across the location. No oil and gas equipment remains on location. Vegetation on location is primarily cereal rye. Vegetation appears reflective of the surrounding area.



Inspection Photos
Location Name: SEVCIK V #27-23
Location ID: 306078



Photo 3. Looking north from the wellhead. Desirable vegetation coverage appears to have reached 80% of the surrounding reference area. Vegetation on location is reflective of the reference area. The table pictured does not appear to be related to oil and gas.



Photo 4. Looking west from the well location. See photo 3 comments.



Inspection Photos
Location Name: SEVCIK V #27-23
Location ID: 306078



Photo 5. Looking south from the well location. See photo 3 comments.



Photo 6. Looking east from the well location. See photo 3 comments.



Inspection Photos
Location Name: SEVCIK V #27-23
Location ID: 306078



Photo 7. Reference area to the southwest of the location.



Photo 8. The tank battery to the southeast was reduced when several surrounding wells were plugged. No equipment remains on the closed portion and reclamation has been conducted. The tank battery does not have a separate location ID but is associated with active well API 123-11302.

