



Site Specific Final Reclamation Completion Notice – Cropland Drone Imagery

Permit Closure Report – Cropland

Location ID: 306516

Location Name: ANDERSON-66N66W/10SENE

Report Date:

9/25/2025

H2E has conducted a thorough review of the data provided in this report. This report was developed in accordance with ECMC Operator Guidance – Operator supplied cropland drone imagery and information for submitting a final reclamation completion notice.

Crop Year and Type

Crop 2025 – Corn

Crop 2024 – Corn

Inspection:

Performed by	H2E Inc.
Date	8/11/2025

All pertinent data, imagery, and materials are included at the end of this report.

Location Checklist



Location Name	ANDERSON-66N66W/10SENE			
Type	Wellhead			
Location ID	306516			
Operator / #	PDC ENERGY INC / 69175			
Field	EATON - #19350			
County, State	Weld, CO			
Lat/Long	40.504140 / -104.756530			
	<input type="checkbox"/> Planned Location	<input checked="" type="checkbox"/>	<input type="checkbox"/> As Drilled	
Location	SENE 10 6N66W 6			
Location Status - Date	PA - 4/7/2021			
Facility Entities	<input type="checkbox"/>	Tank Battery	<input type="checkbox"/>	Pits
	<input checked="" type="checkbox"/>	Wells	<input checked="" type="checkbox"/>	Off-Location Flowlines (Form 44)
	<input type="checkbox"/>	Domestic Taps	<input type="checkbox"/>	On-Location Flowlines (Form 42)
	<input type="checkbox"/>	Electric Utilities	<input type="checkbox"/>	
Equipment on Site	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	Yes
	If yes, list:			
	<input type="checkbox"/>	Pit mouse/rat holes, cellars backfilled		
Access Road	<input checked="" type="checkbox"/>	Regraded	<input type="checkbox"/>	Contoured
	<input type="checkbox"/>	Culverts Removed	<input type="checkbox"/>	Gravel Removed
	Pre-Existing (Must provide supporting documentation):			
Reclamation Status	<input checked="" type="checkbox"/>	Location and associated disturbances reclaimed		
	<input type="checkbox"/>	Subsidence		
Plug date & Form 6S Doc. #:	04/02/2021 - #402711821			
Spills or Releases (Form 19)	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	Yes
Remediation (Form 27/27A)	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Yes
On-Location Flowlines	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	Yes
Off-Location Flowlines	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Yes
Inspection Corrective Actions	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Yes
Variance Requests	No variance requests identified for this location.			
Sundry Notice (Form 4)	No sundry notice pertaining to series 900-1200 rules was identified.			
On Location Flowlines (Form 42)	N/A			
Off-Location Flowlines (Form 44)	Form 44 Doc # & Date: #402823460 - 9/27/2021			
	Purpose: FLOWLINE SYSTEM ABANDONMENT VERIFICATION			
	Abandonment Date: 5/28/2021			
	ECMC Approval Date & Signee: 10/24/2022 - Director of ECMC			
	Operator Comments:			
	Flowline Facility Information			
	ECMC Flowline ID: 479253			
	Operator Flowline ID: PDC Flowline System			
	Status & Date: Abandoned-In-Place 5/28/2021			
	Flowline Type: Well Stream			
	Type of Fluids Transported: Produced Fluids			
	Start Point Location ID: 306516			
	Start Point Riser Lat/Long: 40.504140 / -104.756530			
	Equipment at Start Point: Wellhead			
End Point Location ID: 471973				
End Point Riser Lat/Long: 40.503067, -104.759364				
Equipment at End Point: Separator				

Field Inspection Form (Form INSP)	Form INSP Doc # & Date: 1) #696100429 - 03/09/2019 2) #696100568 - 03/20/2019
	Status Summary: 1) - FOLLOW UP INSPECTION REQUIRED 2) - THIS IS A FOLLOW UP INSPECTION. NO FOLLOW UP INSPECTION REQUIRED
	Inspected Facilities: 1) 289323 2) 289323
	Inspection Status: 1) TA 2) TA
	Inspection Date & Inspector: 1) 3/8/2019 Evins, Bret 2) 03/20/2019 Evins, Bret
	Comments: 2) 03/20/2019 - This is a WELL Inspection. Well is TA. Centralized Battery serves 3 Location IDs (306517, 305912, 306516). Refer to FIR #696100425 and/or Location ID #306517 for Battery / Facility, Equipment info. Follow-up to FIR #696100429 dated 03/08/2019. 1 of 1 Corrective Actions has been addressed. 1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See photo #1. Unused Equipment at wellsite has been removed. See photo #2. No Corrective Actions observed on this FIR.
Inspection Corrective Actions (CAs)	Remove unused equipment at wellsite. Comply w/ Rule 603.f.
Spill or Release (Form 19)	No Form 19's identified for this location.
Site Investigation and Remediation Workplan (Form 27/27A)	Remediation Project #: 17812
	Form 27 Initial Doc # & Date: #402654632 - 04/16/2021
	Purpose: Wellhead Closure and Flowline Abandonment
	Notes: This Form 27 serves as notification for the abandonment of the Anderson 42-10 wellhead and associated flowline that will be abandoned in place. Abandonment activities are planned to begin the week of May 3, 2021.
	Form 27 Supplemental Docs # & Date: #402775092 - 02/08/2022
	Purpose: Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
	Operator Comments: Based on the analytical results and field observations recorded during the closure and abandonment of the Anderson 42-10 wellhead and associated flowline, PDC is submitting a closure request for this location.
	ECMC Comments:
	ECMC COAs: Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required.
	Closure Request Approved: 2/9/2022
Final Resolution: 02/09/2022 - RICK ALLISON	

COGIS Tank Facilities Information (Scout Card)	Tank Battery Name: Anderson/31, 32, 42-10
	Location ID: 471973
	Status & Date: AC - 2/26/2020
	Lat/Long: 40.503052, -104.758871
	Notes:
	No sundry notice pertaining to series 900-1200 rules Form 4 Doc # & Date: was identified for the tank battery.
Purpose: N/A	
COGIS Well Information (Scout Card)	Well Name: ANDERSON #42-10
	Facility ID: 289323
	Well API #: 05-123-24819
	Status & Date: PA - 4/7/2021
	Lat/Long: 40.504140, -104.756530
	Notes:
No sundry notice pertaining to series 900-1200 rules Form 4 Doc # & Date: was identified for the tank battery.	
Purpose: N/A	
Drone Information	Make & Model: DJI M3E MultiSpectral
	Image Processing Software: Pix4D Mapper
	Pilot Name & FAA Certificate #: Ian Hattabaugh - 5069217
	Date of FAA Certificate Issuance: 10/4/2024



Imagery Sources

The following imagery sources were reviewed during this investigation:

NAIP Imagery from 2009-2023, and historic Google Earth imagery from 1985-2023.

Site Observation Notes

No Additional Information

Closure Information

This final reclamation completion notice is intended to close the ANDERSON-66N66W/10SENE (306516) location which consists of the ANDERSON #42-10 (API # 05-123-24819) wellhead. This wellhead does not share a disturbance with any other wells or tank batteries. There is one off-location flowline associated with this well that transported produced fluids to the associated tank battery, and was abandoned-in-place in May of 2021. The associated tank battery has its own location ID (471973) which will remain open until final reclamation has been achieved.

ANDERSON #42-10 was reclaimed and returned to the landowner for agricultural use in 2021. The wellhead was accessed from an unpaved access road that originated at an existing agricultural service road off of County Road 33. The access road was reclaimed and returned to agriculture in conjunction with the reclamation of the well location.

A Remediation Workplan (Form 27-I) was documented on 04/16/2021 for wellhead closure and flowline removal. On 02/08/2022 a Form 27-S (Doc. # 402775092) was filed. This remediation workplan was closed by Rick Allison on 2/9/2022.

One corrective action (CA) was identified during the records review. The CA came from an inspection on 3/8/2019 by Bret Evans, noting unused equipment at the well site in violation of Rule 603.f. The CA was addressed during the following inspection on 03/20/2019 conducted by Bret Evans.

No Spill or Release (Form 19) was identified for this location.


Drone imagery confirms that no equipment was left on site at this location after reclamation activities occurred.

Pre-Plugging Active Operations Location Overview



PDC Form 4 Final Reclamation - Pre Plugging Overview

ANDERSON-66N66W/10SENE




Editor: EJanak
File: PDC_PrePlugging_v1

Scale: 1:2,000
Date: 10/23/2025

- Well Head
- Flowline - Abandoned
- Access Road - Reclaimed
- Reclaimed Tank Battery
- Reclaimed Well Pad
- Major Road
- Weld Local


NAIP 2009 Imagery





PDC Form 4 Final Reclamation - Pre Plugging Overview

ANDERSON-66N66W/10SENE





Editor: EJanak
File: PDC_PrePlugging_v1

Scale: 1:2,000
Date: 10/23/2025

- Well Head
- Flowline - Abandoned
- Access Road - Reclaimed
- Reclaimed Tank Battery
- Reclaimed Well Pad
- Major Road
- Weld Local

NAIP 2009 Imagery





Post-Plugging and Abandonment Location Overview



PDC Energy Form 4 Final Reclamation - Post Plugging Overview

ANDERSON 42-10




Prepared by:
Scale: 1:2,100
Date: 11/12/2025

Editor: EJanak
File: PDC_PostPlugging_v1

- Well Head
- Flowline - Abandoned
- Access Road - Reclaimed
- Reclaimed Tank Battery
- Reclaimed Well Pad
- Major Road
- Weld Local



2025 Drone Imagery





PDC Energy Form 4 Final Reclamation - Post Plugging Overview


ANDERSON 42-10



Prepared by:
Scale: 1:1,300
Date: 11/12/2025

- Editor: EJanak
- File: PDC_PostPlugging_v1
- ⊕ Well Head
- - - Flowline - Abandoned
- Access Road - Reclaimed
- ▭ Reclaimed Well Pad
- Major Road
- Weld Local

2025 Drone Imagery



Cardinal Direction Drone Photos

Photo Dates:

8/11/2025

Drone Photo Height:

85'

North of Disturbance Facing South
Lat/Long: 40.50487353 / -104.75655189



South of Disturbance Facing North
Lat/Long: 40.50339597 / -104.75655678



West of Disturbance Facing East
Lat/Long: 40.50414175 / -104.75751753



East of Disturbance Facing West
Lat/Long: 40.50413658 / -104.75561281



Access Road Drone Photo

Photo Dates:

8/11/2025

Drone Photo Height:

85'

Access Road Facing South

Lat/Long: 40.50410678 / -104.75610672



Flowline Drone Photo

Photo Dates:

8/11/2025

Drone Photo Height:

85'

Flowline Facing West

Lat/Long: 40.50410719 / -104.75610722



Reference Photo for Crop Growth Stage

Cropland Reference Photo (Corn)
Lat/Long: 40.502944/ -104.756278



08/11/2025