

Inspection Photos

11/07/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 335799

Inspection Doc: 718100972

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 1: Photos taken from the west end of the Location; photos provide an overview of the working pad surface from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799




Photo 3: Photo taken next to the wells on the north end of the Location, facing north. Dotted yellow line shows the area where subsidence is developing on the Location and cracking is evident. Stormwater ponding is also apparent within these areas; unclear if stormwater is the source of the subsidence/sinking, or if ponding is facilitating the degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 4: Continued from photo 3. Arrow shows cracks developing around areas of observed subsidence.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 5: Continued from photo 3. Arrow shows cracks developing around areas of observed subsidence.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 6: Photo taken from the northeast end of the Location, facing northeast. Photo shows additional reclamation efforts have been taken by Operator. Areas appear to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 7: Photo shows the tank battery and separator facility on the southern areas of the Location. Secondary containment has been maintained and appears to be in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335799



Photo 8: Photo taken from the housing unit on the southeast end of the Location. Pipe next to housing has been capped to prevent wildlife access.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources