

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/13/2025

Document Number:

701104304

FIELD INSPECTION FORM

Loc ID: 335687 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:


Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
,		ecmc.inspections@qb-energy.com	
Heil, John		john.heil@state.co.us	
		annie.chaivre@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Popejoy, Dusty		dusty.popejoy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260568	WELL	PR	03/01/2019	GW	045-07868	UNOCAL 24-9DRD	EG
260569	WELL	TA	09/01/2021	GW	045-07856	UNOCAL 14-9D	EG
287571	WELL	PR	03/01/2019	GW	045-13000	UNOCAL-ENCANA 13D-9D	EG
287867	WELL	SI	07/01/2025	GW	045-13080	UNOCAL-ENCANA 14D-9D	EG
287882	WELL	PR	07/01/2024	GW	045-13083	UNOCAL-ENCANA 14B-9D	EG
287883	WELL	SI	02/01/2025	GW	045-13082	UNOCAL-ENCANA 14A-9D	EG
287884	WELL	PR	09/01/2019	GW	045-13081	UNOCAL-ENCANA 24D-9D	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
 Ongoing gas leaks at well heads.
 See 06/06/2025 Inspection 708906695 for corrective actions.
 Video of gas bubbling in cellars attached and Gas reading captures from cellars/conductors in photo log.



Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 260568 Type: WELL API Number: 045-07868 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 260569 Type: WELL API Number: 045-07856 Status: TA Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287571 Type: WELL API Number: 045-13000 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287867 Type: WELL API Number: 045-13080 Status: SI Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287882 Type: WELL API Number: 045-13083 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287883 Type: WELL API Number: 045-13082 Status: SI Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287884 Type: WELL API Number: 045-13081 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104316	Video of gas bubbling in cellars from conductors	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7330576
701104317	Flowline integrity inspection 701104304 photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7330577