

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/07/2025

Document Number:

701104311

FIELD INSPECTION FORM

Loc ID: 421340 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Wheeler, Steven		steven.wheeler@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421341	WELL	PR	04/30/2012	GW	045-20360	Cascade Creek 697-05-28B	EG

General Comment:

Flowline Integrity Inspection (Follow Up)
From 08/22/2025 inspection 701104244: 2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left. Unused equipment has been picked up and removed.
From 08/22/2025 inspection 701104244: A 3" buried poly line has been cut off and left running under surface down to CC 0605-02 Pad ID# 323998. Line is open ended with no OOSLAT in place.
No visible sign of 3" poly line at time of this inspection. Form 42 received 9/11/2025 doc # 404350746 to abandon in place.
Timbers and tee posts left behind.
Comply with 606 CA Date 11/22/2025

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	From 08/22/2025 inspection 701104244: 2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left.		
	Unused equipment has been picked up and removed.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Timbers and tee posts left behind.		
Corrective Action:	Comply with 606	Date:	11/22/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 421341 Type: WELL API Number: 045-20360 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404428447	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322987
701104312	Flowline integrity inspection 701104311 photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322984