

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/07/2025

Document Number:

715203345

FIELD INSPECTION FORM

Loc ID 314206 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	
Harms, Jason		Jason@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228026	WELL	PR	01/01/2018	GW	099-06353	HOFFMAN 2-31	PR

General Comment:

This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by separator		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank only has capacity label		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 12/05/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fence around wellhead		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire fence around tank, separator and meter shed. Fence is in disrepair and needs fixed immediately. The pasture is actively being grazed and cattle inside fencing around meter shed at time of inspection		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: 11/10/2025

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Separator is on south side of tank		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter shed is on east side of water tank		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		37.913990,-102.506710

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: Berms need maintenance for capacity				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 12/05/2025

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 228026 Type: WELL API Number: 099-06353 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. There was an audible gas leak detected on the north side of the separator on the 90 degree elbow of the 1/4" line for the regulator.

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/10/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access has deep tracks and needs to be maintained](#)

Corrective Action: [Repair and maintain access](#)

Date: 12/05/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404427551	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322057
715203363	wellhead photo	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322051
715203364	separator and tank	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322052
715203365	separator leak at 1/4" line on regulator	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322053
715203366	meter shed	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322054