

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2025

Submitted Date:

11/14/2025

Document Number:

716301701

FIELD INSPECTION FORM

Loc ID 333417 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287035	WELL	SI	06/01/2025	CBM	071-09006	ULIBARRI 32-6 R	SI

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED		Date:
Type	WEEDS		
Comment:	PHOTO 3: WEEDS OVERGROWN AROUND LOCATION. PHOTO 4: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD.		
Corrective Action:	WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 606. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	PHOTO 6: THE CA FOR OILY WASTE IN PRIME MOVER ENGINE SKID HAS BEEN ADDRESSED HOWEVER THESE ENGINE SKIDS SHOULD BE CLEANED AND MAINTAINED IN BETER CONDITIONS TO PREVENT STORMWATER FROM MIXING WITH OILY WASTE AND CAUSING RULE VIOLATIONS AFTER EVERY STORM EVENT.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:	PHOTO 7: ANCHOR MARKER IS DOWN ON THE NORTHEAST ANCHOR FROM WELLHEAD.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:
Type: Ancillary equipment	# 1		

Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 287035 Type: WELL API Number: 071-09006 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/19/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 IS ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSP. TO INSP. #716301186, THE CA FOR OILY WASTE IN SKID HAS BEEN ADDRESSED HOWEVER THE OTHER CA'S HAVE NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED.</p> <p>ECMC Inspection Report Summary On Tuesday 11-14-2025 at approximately 10:09, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location ULIBARRI 32-6 R API# 05-071-09006 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: WEED MAINTENANCE, RULE 606, 2ND NOTICE IMMEDIATE ACTION REQUIRED. NO ANCHOR MARKER, RULERule 1003.a. 2ND NOTICE IMMEDIATE ACTION REQUIRED. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	11/14/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301702	INSP. PHOTOS	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7331690