

Inspection Photos

11/07/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 335656

Inspection Doc: 718100976

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 1: Photos taken from the west end of the Location; photos provide an overview of the working pad surface from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 3: Photos taken from the wells. Operator has placed a single sign on the north end of the wells. Signage has not been posted at each wellhead pursuant to Rule 605.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 4: Photo shows taken from the interim areas on the west end of the Location, facing north and south respectively. Vegetation appears to be progressing towards 1003.e standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 5: Photo shows taken from the interim areas on the east end of the Location, facing north and south respectively. Vegetation appears to be progressing towards 1003.e standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 6: Photo shows culvert and sediment traps at the Location entrance on the north end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 7: Photo shows the outlet point for the sediment trap on the north end of the Location (east side of road/culvert) appears to be higher in elevation than the inlet and WPS; additional investigation and review of the BMP advised to ensure outlets are functioning as intended.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 8: Photo shows the multiple retention basins observed on the north/northeast end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335656



Photo 9: Photo shows the retention basin observed on the northwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources