

# Inspection Photos

11/07/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 335668

**Inspection Doc:** 718100978

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 1:** Photos taken from the south end of the Location; photos provide an overview of the working pad surface from west, northwest, northeast to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 3:** Photos taken from the western interim areas of the Location. Areas are not progressing towards 1003.e standards; slopes remain predominantly bare and exposed soils, and lack stabilization; cuts remain evident and soils do not appear to have been replaced to their original relative grade. Areas appear to be the former K26 pit site.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 4:** Photos taken from the wells. Operator has placed a single sign on the north end of the wells. Signage has not been posted at each wellhead pursuant to Rule 605.d.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 5:** Photos show trailered equipment next to separators/gas lifts. Equipment appears to be leaking resulting in spills onto the WPS.



Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 6:** Continued from photo 5. Photo shows open ended hose equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 7:** Photo shows fluids spilled within containment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 8:** Photo taken from the tank facility on the northeast end of the Location. Hole/tear observed within the northwest corner of the liner.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 335668



**Photo 9:** Photo taken from the pipeline equipment on the northeast end of the Location. Corrosion evident at the base of the secondary containment BMP. ECMC staff have concerns regarding the integrity and imperviousness of the containment measure.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources