

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2025

Submitted Date:

11/14/2025

Document Number:

700300871

**FIELD INSPECTION FORM**

Loc ID 325420 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 5852  
Name of Operator: BAIRD\* JERRY  
Address: 989 HIGHWAY 140  
City: HESPERUS State: CO Zip: 81326

**Findings:**

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Arleen		arleen@walsheng.net	SW Inspections
Longworth, Mike		michael.longworth@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214744	WELL	AC	09/29/1999	DM	067-06348	TALLEY 1	PR

**General Comment:**

On 10/23/25 ECMC SW Compliance SA supervisor conducted an inspection of the Tally 1 domestic well. An audit of electronic well file found annual registration and bradenhead testing compliant. There was no Form 44 domestic tap data found in well file.

A routine optical gas imaging survey was conducted. Some wellhead fittings and gaskets appeared weathered and not maintained. A gas leak was observed near a dry, cracked rubber gasket in wellhead.

Some supplies, parts, debris at wellhead

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	some information becoming faded		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Parts and tools observed at and around wellhead		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 1	corrective date	
Comment:	meter shed, appears to be former midstream, not in use, did not appear to have flowlines or meter although door was overgrown		
Corrective Action:			Date:
Type: Other	#		
Comment:	domestic gas tap		
Corrective Action:	Register domestic tap via Form 44 with address or addresses of residential building unit (s) where gas is delivered and used per Rule 1101.c		Date: <u>02/15/2026</u>
Type: Ancillary equipment	#		
Comment:	odorant system/mercaptan pot		
Corrective Action:			Date:
Type: Other	#		
Comment:	wellhead, see "optical gas imaging" and photo document		
Corrective Action:	repair/maintain wellhead fittings		Date: <u>02/15/2026</u>
Type: Flow Line	# 1		
Comment:	Inactive midstream riser on east side of distrubed area		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Active gas distribution with regulator		
Corrective Action:			Date:
Type: Bradenhead	#		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	see "optical gas imaging" and "attachment" sections for details and corrective action on wellhead leak, unrepaired leaks can also be considered "venting" even if unintentional.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 214744 Type: WELL API Number: 067-06348 Status: AC Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Last test conducted and submitted on 3/28/25

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Other						wood chips/pieces

Comment: Disturbed area is covered and stabilized with small wood chips and pieces with along with grass revegetation

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

