

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2025

Submitted Date:

11/14/2025

Document Number:

719000929

FIELD INSPECTION FORM

Loc ID: 326148 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215948	WELL	PR	01/01/2003	CBM	067-07554	HUBER-HECHT 1-4	PR

General Comment:

Inspection Report Summary
On 11/14/25 I Inspector Charles Garcia conducted an on-site follow up inspection.
Location: HUBER-HECHIT 1-4
API# 067-07554
Operator: HILLCORP ENERGY COMPANY
County: LaPlata
DOC#719000883
FIR #404427962 CA'S RESOLVED SEE LOCATION PICTURES

Location

Overall Good:

Signs/Marker:

	Type TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK PLACARD SUN DAMAGED AND NOT LEIBLE SEE LOCATION PICTURES Install sign or correct sign per rule 605 CA RESOLVED SEE LOCATION PICTURES		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.245600,-107.756600
Comment:	30 BBL PRODUCED WATER TANK HAS VERY LITTLE PAINT ON TOP OF TANK STARTING TO RUST SEE LOCATION PICTURES 600.b MAINTAIN TANK PAINT CA RESOLVED SEE LOCATION PICTURES				
Corrective Action:		Date:			

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input style="width: 95%;" type="text"/>			
Corrective Action:		Date:		

Venting:

Yes/No	<input style="width: 95%;" type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type	<input style="width: 95%;" type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 215948 Type: WELL API Number: 067-07554 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000930	LOCATION PICTURES	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7333114