

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2025

Submitted Date:

11/15/2025

Document Number:

713401111

**FIELD INSPECTION FORM**

Loc ID 433287 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		ECMCInspectionReports@flywheelenergy.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438346	WELL	SI	08/01/2024	GW	103-12142	FEDERAL RGU 331-26-198	SI

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: Access		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type CONTAINERS		
	Comment: Chemical tank		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 970-285-9377/911		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type OTHER		
	Comment: Chemical tank - Hog panels		
Corrective Action:			Date:
	Type TANK BATTERY		
	Comment: Hog panels		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment: <a href="#">Workover Rig and all associated equipment</a>			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">Chemical tank</a>			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: <a href="#">Pressure transducer located on bradenhead, bradenhead valve is accessible</a>			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment: <a href="#">Rig tank</a>					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	250 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLs	OTHER		,
Comment: <a href="#">Frac tanks</a>					
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 438346 Type: WELL API Number: 103-12142 Status: SI Insp. Status: SI

**Cement**

Cement Contractor

Contractor Name: ENSIGN

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: FORM 42 document #404422324 - Observed plugging operations TOH on FEDERAL #RGU 331-26-198 well.

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				Sparse
		Compaction				
Gravel						Sparse
				Material Handling And Spill Prevention		Chemical tank
		Ditches				
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 11/7/2025 at approximately 11:52 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL/RGU 43-23-198 PAD at Location ID #433287 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed plugging operations TOH on FEDERAL #RGU 331-26-198 well.</p> <p>Limited inspection/audit due to ongoing plugging operations on location.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	11/15/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401112	713401111 Inspection-Audit Photos	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7333377">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7333377</a>