

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2025

Submitted Date:

11/16/2025

Document Number:

708907881

**FIELD INSPECTION FORM**

Loc ID 322541 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone | Email                                    | Comment |
|-------------------|-------|--|---------|
| Katz, Aaron       |       | aaron.katz@state.co.us                   |         |
| Haverkamp, Curtis |       | curtis.haverkamp@state.co.us             |         |
| TEP               |       | ECMCInspectionReports@flywheelenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210760      | WELL | PR     | 10/12/1986  | GW         | 045-06518 | ARCO W-23-35  | PR          |

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 210760 Type: WELL API Number: 045-06518 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

Date: 12/16/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p><b>CECMC Inspection/Audit Report Summary</b><br/>                     On 11/16/2025 at approximately 16:34 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of TEP ROCKY MOUNTAIN LLC ARCO W-23-35 Location # 322541 in Garfield County Colorado.<br/>                     Location is within High Priority/Density Habitat areas/Bald Eagle Roost Site &amp; in close proximity to Bald Eagle Nest Site.<br/>                     Location is within Rule 411a Surface Water External Buffer.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - Well lacks wellbore diagram - Comply with Rule 420 with a CA date of 12/16/2025</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.<br/>                     This is a summary of desktop inspection/audit report.</p> | smelserw | 11/16/2025 |