

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/10/2025

Document Number:

693808995

**FIELD INSPECTION FORM**

Loc ID 322436 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10770  
Name of Operator: VISION ENERGY LLC  
Address: P O BOX 370  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 15 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	
Ramsey, Scott		scott.ramsey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210507	WELL	SI	05/01/2012	GW	045-06263	BALDY CREEK-FEDERAL 2-20	TA
475632	OFF-LOCATION FLOWLINE	AC	08/08/2022		-	Production Line 20NWNE	AC

**General Comment:**

[ECMC Inspection/Audit Report Summary](#)

On October 28, 2025, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection/audit for Vison Energy LLC - 10770 on the Baldy Creek Federal 2-20 well, API#05-045-06263, LocID#322436, in Garfield County, Colorado.

The well was shut in at time of inspection.

During the inspection/audit, the following compliance issues were observed:

- 1) Unused equipment and junk on location
- 2) Unmarked guyline anchors (3)
- 3) Past due MIT to maintain SI/TA status

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	CO Rd 312		
Corrective ActionL			Date:
Type	Access		
comment:	CO Rd 328		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-0082		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected storage tank with hatches removed.		
Corrective Action:	Comply with Rule 606. CA from previous inspection (Doc#707801640 on 6/3/2025) not completed. CA date remains as before.		Date: <u>06/23/2025</u>
Type	STORAGE OF SUPL		
Comment:	Unused pipe fencing		
Corrective Action:	Comply with Rule 606. Comply with Rule 606. CA from previous inspection (Doc#707801640 on 6/3/2025) not completed. CA date remains as before.		Date: <u>06/23/2025</u>
Type	OTHER		
Comment:	Open ended piping and manways on tank/available for entry by wildlife		
Corrective Action:	Eliminate possibility of wildlife to enter. CA from previous inspection (Doc#707801640 on 6/3/2025) not completed. CA date remains the same		Date: <u>06/23/2025</u>
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Fencing torn down on one side		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Meter run for Federal 2-20 shut in. No Chart or calibration. Meter run for Federal 3-28 (located 1.25 mile SE), operational with chart and current calibration card.		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	11/24/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	300 BBLs	STEEL AST		39.435134,-107.462335
Comment:	Unused equipment. See Housekeeping section above for CA.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number	
045-06280	

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210507 Type: WELL API Number: 045-06263 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Last productio 9/2011. Noticed inactive 12/21/2022.  
 Last MIT 8/22/2016.  
 Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

**Corrective Action:** Produce well after performing successful mechanical integrity test per Rule 417 or plug well.  
 To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.  
 CA from last inspection (Doc#707801640 on 6/3/2025) not completed. CA date remains the same.

Date: 07/18/2025

**BradenHead**

Date of Last Brhd Test: 06/23/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
 End Surf Csg Pressure: 0

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 475632 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
1) Unused equipment and junk on location 2) Unmarked guyline anchors (3) 3) Past due MIT to maintain SI/TA status	browninc	11/10/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404430413	INSPECTION SUBMITTED	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325519">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325519</a>
693808996	Inspection photos 11/3/2025	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325517">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325517</a>