

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/10/2025

Document Number:

693808997

FIELD INSPECTION FORM

Loc ID 322445 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ramsey, Scott		scott.ramsey@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210524	WELL	SI	08/01/2020	GW	045-06280	BALDY CREEK FEDERAL 3-28	PR

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On November 3, 2025, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection/audit for Vison Energy LLC - 10770 on the Baldy Creek Federal 3-28 well, API#05-045-06280, LocID#322445, in Garfield County, Colorado.

Normal production operations were observed.

During the inspection/audit, the following compliance issues were observed:

- 1) Unmarked guy line anchors

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Main		
comment:	Co Rd 328		
Corrective ActionL			Date:
Type	Access		
comment:	Co Rd 312		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-0082		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pipe and hose around separators		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	#		corrective date
Comment:	Meter on pad with Baldy Creek Federal #2-20 well (LocID#322436) 1.25 mi NW. Calibration card and chart up to date. CA completed.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:	Old separator removed and replaced with 2.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Type: Flow Line	# 1		
Comment:	Off location flowline to pad with Baldy Creek Federal #2-20 well (LocID#322436) 1.25 mi NW.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Unmarked guy line anchors (3).		
Corrective Action:	Install proper guy line markers per Rule 1003.a. CA from previous inspection Doc#707801639 on 6/4/2025 not completed. CA date remains the same.		Date: <u>06/23/2025</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210524 Type: WELL API Number: 045-06280 Status: SI Insp. Status: PR

Producing Well

Comment: [Last production recorded 11/2020.](#)
[Form 42 Doc#404345096 approved 9/8/2025 to return to production.](#)

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/23/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 50 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
1) Unmarked guy line anchors	browninc	11/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404430414	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325520
693808998	Inspection photos 11/3/2025	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325518