

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/10/2025

Document Number:

693808999

FIELD INSPECTION FORM

Loc ID 322404 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Ramsey, Scott		scott.ramsey@state.co.us	
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210419	WELL	TA	11/01/2020	GW	045-06175	BALDY CREEK UNIT 1-17	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On November 3, 2025, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection/audit for Vison Energy LLC - 10770 on the Baldy Creek Unit #1-17 well, API#05-045-06175, LocID#322404, in Garfield County, Colorado.

Well was found in Temporily Abandoned status.

During the inspection/audit, the following compliance issues were observed:

- 1) Unmarked guy line anchors
- 2) Inadequate secondary containment around produce water tank
- 3) Open ended lines and risers

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Main		
comment:	CO Rd 328		
Corrective ActionL			Date:
Type	Access		
comment:	CO Rd 328		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Wrong contact number on tank label.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-0082		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended lines and riser at various locations.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA from previous inspection Doc#707801638 on 6/3/2025 not completed. CA date remains the same.		Date: 11/09/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Pipe fence around separator.		
Corrective Action:			Date:
Type	TANK BATTERY		

Comment:	Pipe barricade at tank heater			Date:	
Corrective Action:				Date:	
Equipment:					corrective date
Type:	Gas Meter Run	# 2			
Comment:					
Corrective Action:				Date:	
Type:	Pump Jack	# 1			
Comment:					
Corrective Action:				Date:	
Type:	Horizontal Heated Separator	# 1			
Comment:					
Corrective Action:				Date:	
Type:	Bird Protectors	# 2			
Comment:					
Corrective Action:				Date:	
Type:	Dehydrator	# 1			
Comment:	Open access door				
Corrective Action:				Date:	
Type:	Bradenhead	# 1			
Comment:					
Corrective Action:				Date:	
Type:	Deadman # & Marked	#			
Comment:	Unmarked guy line anchor				
Corrective Action:	Install proper guy line markers per Rule 1003.a			Date:	11/24/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		39.446826,-107.468133
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Secondary containment is insufficient.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1). CA from previous inspection Doc#707801638 on 6/3/2025 not completed. CA date remains the same.			Date:	11/22/2024

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210419 Type: WELL API Number: 045-06175 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/23/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
1) Unmarked guy line anchors 2) Inadequate secondary containment around produce water tank 3) Open ended lines and risers	browninc	11/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404430484	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325672
693809000	Inspection photos 11/3/2025	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7325670