

# Inspection Photos

November 14th, 2025

Operator: Catamount Energy Partners

Location ID: 311991

Inspection Document #: 714002784

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Outpost 33-8  
Location ID: 311991



November 14, 2025  
115° SE



November 14, 2025  
102° E

CATAMOUNT  
ENERGY PARTNERS  
OUTPOST 33-8  
OIL AND GAS LOCATION ID #311911  
EMERGENCY #: (970) 442-6620 OR 911

CATAMOUNT  
ENERGY PARTNERS  
OUTPOST 33-8  
OIL AND GAS LOCATION ID #311911  
EMERGENCY #: (970) 442-6620 OR 911

**Photo 1.** Overview photo of the well pad construction operations and location sign taken from the northwest corner facing center. Scraping and salvaging operations were on going during the time of the inspection.

Inspection Photos  
Location Name: Outpost 33-8  
Location ID: 311991



**Photo 2.** Overview photo of the well pad construction area taken with a drone from the southern edge facing north. It was noted that area (highlighted with red area) immediately east of the existing active pad had not yet been salvaged.

November 14, 2025  
35° NE



**Photo 3.** View of the well pad disturbance taken from the eastern edge of the existing red will pad facing center.

November 14, 2025  
76° E



**Photo 4.** View of the southern edge of the well pad and perimeter BMP wattles. Note: wattles have not been installed per good engineering practices (trenched) in these areas.

November 14, 2025  
28° NE



**Photo 5.** Additional view of perimeter BMP wattles on the southern and eastern edges of the disturbance which have not been installed per good engineering practices (trenched).

Inspection Photos  
Location Name: Outpost 33-8  
Location ID: 311991



**Photo 6.** View of soil pit taken in the eastern portion of the disturbance. It was noted that no more than 6 inches of topsoil were observed on site.

Inspection Photos  
Location Name: Outpost 33-8  
Location ID: 311991

November 14, 2025  
102° E



**Photo 6.** View of cut for topsoil salvage on the location. It appears that the operator is salvaging the 6 inch minimum requirement of topsoil

