

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/11/2025

Submitted Date:

11/17/2025

Document Number:

709100598

FIELD INSPECTION FORM

Loc ID 317097 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Alex Ahmadian		alex.ahmadian@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236210	WELL	PR	08/15/2006	OW	121-08700	JOLLY 2	EI

General Comment:

On November 11, 2025, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, Alex Ahmadian, and Sienna Madurski inspected the JOLLY-63S55W/18NENE (Location ID 317097) and the Jolly 2 wellhead (API 121-08700).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type			
Comment:	Wellhead signage present		
Corrective Action:		Date:	
Type			
Comment:	Unlabeled blue barrel observed on location.		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.		Date: 11/19/2025

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type			
Comment:	Unused equipment location on site.		
Corrective Action:	Copoly with Rule 606		Date: 02/11/2026

Overall Good:

Spills:

Type	Area	Volume		
Comment:	Drips and drabs of hydrocarbons observed around and on the pump jack and around the wellhead.			
Corrective Action:	Cleanup and properly treat or dispose in accordance with Rule 905.e.			Date: 11/20/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 236210 Type: WELL API Number: 121-08700 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100599	Photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334597