

WELL NAME: CENTAUR 24-36, API #: 071-08349, INSP. # 716301711




PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: UNUSED EQUIPMENT (PUMPJACK AND ALL ITS COMPONENTS INCLUDING CEMENT PAD). REMOVE UNUSED EQUIPMENT PER RULE 606. THIS IS THE 2ND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.





PHOTO 4: AREA OF IMPACTED SOIL NEAR WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002, (2).D. THIS IS THE 2ND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.



PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,,(2).D.



PHOTO 6: OILY WASTE IN PRIME MOVER SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002.(2), D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181 CA DATE 11-18-2025.