

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>11/17/2025</u> Submitted Date: <u>11/17/2025</u> Document Number: <u>719000948</u>
FIELD INSPECTION FORM			

Loc ID 306937 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
 Name of Operator: SIMCOE LLC
 Address: 1199 MAIN AVE SUITE 101
 City: DURANGO State: CO Zip: 81301

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280386	WELL	PR	09/30/2005	CBM	067-09077	ROBERT DULIN C 2	PR

General Comment:

[Inspection Report Summary](#)
 On 11/17/25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: ROBERT DULIN C 2
 Operator: Simcoe LLC
 API#: 067-09077
 County: LaPlata
 DOC#719000845
[FRR#404434698 CA RESOLVED SEE LOCATION PICTURES DOC#404434703](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment

#

corrective date

Comment:

TELEMETRY EQUIPMENT
 LUBE OIL CONTAINER WITH SPILL PREVENTION
 SPILL PREVENTION 1/2 FULL WITH STORMWATER SEE LOCATION PICTURES
 "Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored
 and may have some product mixed in, fluid should be disposed as waste in approved
 manner for type of chemical used CA RESOLVED SEE LOCATION PICTURES FIR
 DOC#404434703

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 280386 Type: WELL API Number: 067-09077 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12