

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2025

Submitted Date:

11/11/2025

Document Number:

699700483

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blakeman, Audrey		audrey.blakeman@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	
Jackson, Ben		ben.jackson@state.co.us	
, QB		ecmc.inspections@qb-energy.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Metz, Collin		collin.metz@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: See Form 19 Initial doc 404396406, Form 19 Supplemental doc 404408650 and Form 27 Initial doc 404413122 for additional information. ECMC staff John Heil, Nick Cholas, Ben Jackson, Collin Metz, Kris Neidel and Mike Longworth conducted an environmental inspection of Little Creek and the adjacent areas. Little Creek flow direction is from the southwest to the northeast and runs adjacent and underneath the access road. Areas of potentially impacted material were observed in surface water, soils and vegetation adjacent to Little Creek. A more permanent divergence pipe was observed diverting flow of surface water around areas that appear to be most impacted. Colorado Drilling and Sampling, Inc, HRL Compliance Solutions and Operator personnel were on location advancing soil borings and collecting soil samples. See attached Photo Location Map and Photo Log for details.

Corrective Action: Comply with COAs on approved Form 19 Initial doc 404396406 and Form 19 Supplemental doc 404408650.

Date: _____

Reportable: YES

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404431964	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7326840
699700484	20251104 Photo Location Map	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7326835
699700487	20251104 Photo Log	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7326836