

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/18/2025

Document Number:

720900227

FIELD INSPECTION FORM

Loc ID 303899 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253767	WELL	PR	03/21/1995	GW	125-07645	JOE BROPHY 8-14	PR

General Comment:

Inspector completed Follow-up audit 11/03/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 1/14/2025 FIR document number 698603030. Operator has submitted FIRR. All corrective actions identified in FIR has been completed.

Location

Lease Road:

Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
In Containment:	No				
Comment:	<input style="width: 100%;" type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					

Fencing/:

Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.			
	Corrective action completed.			
Corrective Action:			Date:	
Type: Prime Mover		# 1		
Comment:	Electric Motor.			
Corrective Action:			Date:	
Type: Bradenhead		# 1		
Comment:	Bradenhead plumbed to surface.			
Corrective Action:			Date:	
Type: Gas Meter Run		# 1		
Comment:	Remote Gas Meter Run located on CR 51. Gas Meter Run. Chart in Meter Box dated 11-1-25. Well Inlet Valve open. Gas Outlet Valve open.			
Corrective Action:			Date:	
Type: Dehydrator		# 1		
Comment:	Dehydrator (Drip Bottle) at wellhead to gas meter run inlet.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:	Corrective action completed.		
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Location Construction

Location ID: 253767 CDP: _____

Comment:

Corrective Action: Date: _____

Form 2A COAs:

Comment: No COA's.

Corrective Action: Date: _____

Wildlife BMPs:

Comment:

Corrective Action: Date: _____

Comment:

Corrective Action: Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 253767 Type: WELL API Number: 125-07645 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run
Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 9/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720900242	Inspection photos.	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7337324