

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2025

Submitted Date:

11/18/2025

Document Number:

716301721

FIELD INSPECTION FORM

Loc ID 309380 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10455
Name of Operator: KCPI LLC
Address: 621 17TH STREET #1445
City: DENVER State: CO Zip: 80293

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Abrams, Deborah		deborah.abrams@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432424	WELL	EP	04/09/2015	LO	071-09915	WINTERS 2	PA

General Comment:

"This is a field audit of the scout card, related documents and the location."

Inspected Facilities

Facility ID: 432424 Type: WELL API Number: 071-09915 Status: EP Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: YES Pit ID: Lat: 37.271732 Long: -104.473853

Reference Point: SE Other: _____ Length: 80 Width: 60

Lining:

Liner Type: Liner Condition:

Comment: PHOTO 5: PIT LINER IS COMPROMIZED AND NOT MAINTAINED. NO PIT PERMIT IN WELL FILE

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment: NONE

Corrective Action

Date:

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301722	INSP. PHOTOS	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7337637