

Inspection Photos

11/11/2025

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096

Inspection Doc: 718101000

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 1: Photos taken from the northeast end of the Location. Photo shows subsidence/stabilization issues.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 2: Photos show safety fencing inadequate to prevent wildlife access to the excavated areas. No other BMPs to prevent wildlife access to, or allow wildlife egress from, the excavated areas observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 3: Photos taken from the tank battery. Photos show fluid accumulation and wildlife mortality observed within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 4: Lines at tank have not been capped or plugged.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 5: Photo shows BMPs to stabilize the working pad surface, as well as to minimize vehicle tracking and sediment transport show signs of disrepair, and do not appear to be sufficient. Maintenance advised to ensure BMPs remain in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



Photo 6: Photo taken from ditch/berm on the west end of the Location. Sediment accumulation within the ditch is apparent. Maintenance advised to ensure stormwater discharge can continue, and ponding on the pad is prevented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources