

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/18/2025

Document Number:

717000592

FIELD INSPECTION FORM

Loc ID 319736 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201184	WELL	SI	01/01/2019	GW	001-06587	BRUCHEZ 3	TA

General Comment:

[Routine inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: STORAGE OF SUPL

Comment:

Corrective Action:

Date: 12/19/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment:

Comment:

Multiple Spills and Releases?

Venting:

Yes/No:

Comment:

Corrective Action:

Date:

Flaring:

Type:

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201184 Type: WELL API Number: 001-06587 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/11/2025 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to ther surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On November 5th 2025 at approximately (11:30 am). I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: RENEGADE OIL AND GAS Location name: BRUCHEZ #3 API # 001-06587 Location ID #: 319736 County: Adams While there, I observed TA well. During this inspection the following possible compliance issues were observed: Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment). Corrective Action Date 12/19/2025. See attached photos</p> <p>A follow-up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000593	Inspection photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7338481