

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/12/2025

Document Number:

701104313

**FIELD INSPECTION FORM**

Loc ID: 323998    Inspector Name: LONGWORTH, MIKE    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
 Name of Operator: LARAMIE ENERGY LLC  
 Address: 1700 LINCOLN ST STE 3950  
 City: DENVER    State: CO    Zip: 80203

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone        | Email                                 | Comment         |
|--------------------|--------------|---------------------------------------|-----------------|
| COGCC, Laramie     | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |
| Schlagenhauf, Mark |              | mark.schlagenhauf@state.co.us         |                 |
| Trujillo, Aaron    |              | aaron.trujillo@state.co.us            |                 |
| Wheeler, Steven    |              | steven.wheeler@state.co.us            |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 211450      | WELL | PA     | 09/01/2023  | GW         | 045-07210 | CASCADE CREEK 605-2 | EG          |

**General Comment:**

Follow up to 8/22/2025 Flowline Integrity Inspection  
 Corrective actions have not been addressed.  
 2-4" frac lines running under recontoured location from northwest edge of location to off the south edge of location.  
 2-4" frac lines running along west fence line.  
 Buried black 3" poly line has been cut off in several places with ends sticking out of surface.  
 Register flowlines and out of service flowlines must be abandoned per COGCC rule 1105  
 OOSLAT out of service flowline by no later than end of the day 9/4/25  
 Corrective action date 9/20/25  
 Noxious weeds on reclamation location.  
 Comply with Rule 606  
 Corrective action date 9/20/25

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: [Noxious weeds on reclamation location.](#)

Corrective Action: [Comply with Rule 606](#)

Date: 09/20/2025

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 211450 Type: WELL API Number: 045-07210 Status: PA Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                    | URL   |
|--------------|--|---|
| 404433509    | INSPECTION SUBMITTED                           | <a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328383">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328383</a> |
| 701104314    | Flowline integrity inspection 701104313 photos | <a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328362">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328362</a> |