

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2025

Submitted Date:

11/10/2025

Document Number:

720800134

FIELD INSPECTION FORM

Loc ID: 422413 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422377	WELL	SI	06/01/2024	OW	123-33238	CASTOR LC 27-72HN	SI

General Comment:

This is a Compliance Field Audit of the Scout Card, Related Documents and the Location for an abandoned well on an active Location

Location

Overall Good:

Signs/Marker:

Type BATTERY

Comment: Adequate

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: Unused Pipe, Day Tanks and Secondary Containments, Automation Equipment remain on Location.
* Well appears to have been Plugged and Abandoned, 3 months to remove all surface Equipment has passed.

Corrective Action: Comply with Rule 1004

Date: 12/01/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Barbed Wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run # 2

Comment: Sales and Buy-Back Meters

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 422377 Type: WELL API Number: 123-33238 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Appears to have been Plugged and Abandoned per Form 6S (IN PROCESS) 404217130 dated 05.26.2025 with a Surface Plug Date of 04.01.2025 and a Cut and Cap Date of 04.28.2025
Lastest Quaterly Form 27 - 404375536 dated 10.20.2025

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404433530	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328393
720800135	Photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7328380