

Inspection Photos

API: 017-06410

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 11/18/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. This area was graded with loose soil material from the roadside. The adjacent roadside soils should not be graded, causing the road to widen with additional disturbance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 11/18/2025

Inspection Photos



Photo 2. Facing south along the access road. There has been road base material spread along the road where road degradation had occurred.



Inspection Photos



Photo 3. There are chunks of asphalt from material brought in to build up the road. Also material where inspectors foot is placed is loose and needs to be graded and compacted.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 11/18/2025

Inspection Photos



Photo 4. Facing southwest toward the wellsite. There was an active leak observed at the well which had flowed approximately 120' down to this point from the wellhead.



Inspection Photos



Photo 5. The source of the leak can be seen at red arrow..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 11/18/2025

Inspection Photos



Photo 6. Facing to the northeast at the wellhead. The pumper arrived onsite to turn the valve and stop the leak.



Inspection Photos



Photo 7. Inspection the day before observed a small spill had occurred at the wellhead.



Photo 8. The next day when active sill was occurring, it was observed that the previous spill at area of red circle had been covered up with a drag harrow.

