

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2025

Submitted Date:

11/19/2025

Document Number:

713602456

FIELD INSPECTION FORM

Loc ID 321605 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96730
Name of Operator: WILLIFORD ENERGY COMPANY
Address: 6060 AMERICAN PLAZA SUITE 760
City: TULSA State: OK Zip: 74135

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Storts, Doug		pds@willifordenergy.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Growns, Larry		lgrows@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207475	WELL	IJ	12/30/2011	ERIW	017-06410	RHOADES UNIT TRACT 3 1	RI

General Comment:

This is a follow up reclamation inspection of the RHOADES Unit Tract 3 #1 wellsite.
This was a joint inspection with SE Environmental Specialist onsite.
See attached photos and additional details within this report

Location

Lease Road:

	Type Access		
comment:	<p>There has been material spread along the road to build up eroded areas. It appears material containing asphalt was used which may not be an appropriate material to use. There are some large chunks of asphalt that have fallen outside of the road that will need to be removed and are considered debris.</p> <p>There are also areas of the road that were graded using the roadside soils which has created loose dusty soils. All disturbance and road bed material must be kept within the access road boundary.</p>		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			
Produced Water	WELLHEAD				
Comment:	<p>There was an active produced water leak observed at the wellhead which had flowed approximately 120' down gradient. The Operator was immediately notified by phone call to the emergency contact number. At the same time, a pumper driving by pulled in and was able to shut off the leak at the wellhead. This is a reportable spill that requires Form 19, Spill/Release Report Initial within 24 hours of discovery.</p>				
Corrective Action:	<p>Control and contain spills/releases and clean up per Rule 912.a. Submit a form 19 to Report spill or release of E&P produced fluids. Remove free fluids and contact EPS staff per Rule 912.b.</p>			Date:	11/19/2025
Condensate	WELLHEAD				
Comment:	<p>The day before this inspection a separate site visit was performed which observed a condensate leak at the well. There were fresh drag marks from the drag harrow which covered up the stain soils from the previous day. See photo 7, 8.</p>				
Corrective Action:	<p>Control and contain spills/releases and clean up per Rule 912.a.</p>			Date:	11/19/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There has been material spread along the road to build up eroded areas. It appears material containing asphalt was used. There was also roadbase spread over the asphalt material. The roadbase material along the road needs to be graded, crowned, and compacted. BMP's must be installed per good engineering practice.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602457	Inspection Photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7340510