

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2025

Submitted Date:

11/20/2025

Document Number:

715203438

**FIELD INSPECTION FORM**

Loc ID 317181 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10536  
Name of Operator: SMITH ENERGY LLC  
Address: 1540 MAIN ST SUITE 218 #334  
City: WINDSOR State: CO Zip: 80550

**Findings:**

23 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	
Smith, Chris		smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237054	WELL	PR	01/10/1996	GW	121-09554	THIM 4-14	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign mounted to metal shed and lease sign by meter shed. Sign for the Thim 4-14 needs to be replaced with a sign thats legible or repainted		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs for tanks/pits		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		Date: _____
Corrective Action:	<input style="width: 100%;" type="text"/>		
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Tires are in place around location to deter livestock from tearing up the fence		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds inside fence need to be maintained		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Wire fence around pits, meter sheds and metal sheds		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 0		
Comment:	Removed from inventory		
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	Removed from inventory		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank w/containment		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	2-Separators in metal sheds 1-VGS 50% by Thim 4-14 metal shed 1-VGS buried on west side of Thim 8-14 meter shed		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Removed from inventory		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Thim 4-14 & 8-14		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		39.883200,-102.938800
Comment:	Partially buried fiberglass water tank in the pit for Thim 8-14				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	24bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		39.883300,-102.938700
Comment:	Culvert used as a buried tank in the pit				
Corrective Action:			Date:		

**Paint**

Condition	
Other (Content)	
Other (Capacity)	24bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Berms are inadequate and need to rebuilt around the buried tank				
Corrective Action: Maintain berms for the pit				Date: 12/19/2025

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 237054 Type: WELL API Number: 121-09554 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Shared meter run for Thim 4-14 and 8-14](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: <u>Evaporation</u>	Lined: <u>NO</u>	Pit ID:	Lat: <u>39.883230</u>	Long: <u>-102.938930</u>
Reference Point: <u>SE</u>	Other: _____	Length: <u>20</u>	Width: <u>20</u>	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: Wire fence around pit

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: YES

Comment: 24bbl Fiberglass tank partially buried inside pit. Thim 8-14 (121-10789)

Corrective Action

Date: \_\_\_\_\_

Type: <u>Evaporation</u>	Lined: <u>NO</u>	Pit ID:	Lat: <u>39.883290</u>	Long: <u>-102.938670</u>
Reference Point: <u>SE</u>	Other: _____	Length: <u>30</u>	Width: <u>20</u>	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: Wire fence around pit

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type:	Netting Condition:	
Comment:	<input type="text"/>	
Corrective Action	<input type="text"/>	
Date:		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard: <u>YES</u>
Comment:	<a href="#">24bbl corrugated metal open culvert inside pit. Thim 4-14 (121-09554)</a>	
Corrective Action	<input type="text"/>	
Date:		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203451	location photos	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7342241">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7342241</a>