

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2025

Submitted Date:

11/20/2025

Document Number:

715801682

**FIELD INSPECTION FORM**

Loc ID 328493 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cchew@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248258	WELL	PR	08/01/2025	GW	123-16056	STONEBRAKER 42-12	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign not legible, faded. Install sign to comply with Rule 605.g. CO date 12-20-2025		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type			
Comment:	Dead vegetation throughout location& around equipment needs to be cut & removed per Rule 606. CA date 11-27-2025.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: fabricated square tubing.

Corrective Action:

Date:

**Equipment:**

				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Prime Mover	# 1			
Comment: Electric motor				
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment: electric panel is shut off				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No NO

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 248258 Type: WELL API Number: 123-16056 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, valves closed & electric panel is shut off.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: yes plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 11-20-2025 at approximately 1240 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 328493                      API # 05-123-16056                      Well name: Stonebreaker 42-12                      County: Weld                      Weather: Cloudy                      Temp: 48*                      Location: dry                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606: Housekeeping: dead vegetation needs to be cut &amp; removed from location.                      605.g signs general: Sign faded &amp; needs to be updated.                      Any corrective actions from previous Inspections that have not been addressed are still applicable.                      See attached photos.                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	11/20/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801683	Location photos	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7342337">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7342337</a>