

KPK
Central tank battery
Location ID: 450391



Location



Location

KPK
Central tank battery
Location ID: 450391



Location



ECD not metered

KPK
Central tank battery
Location ID: 450391



Weeds around running ECD



ECD running

KPK
Central tank battery
Location ID: 450391



Tank lacks legible labeling and debris



Tank lacks legible labeling and debris

KPK
Central tank battery
Location ID: 450391



Tank lacks legible labeling and debris



Location

KPK
Central tank battery
Location ID: 450391



Chemical tanks lacking legible labeling



Chemical tanks lacking legible labeling

KPK
Central tank battery
Location ID: 450391



Location

Staining

KPK
Central tank battery
Location ID: 450391



Tank that was leaking emissions



Staining

KPK
Central tank battery
Location ID: 450391



Debris



Crack in tank sealed with fiberglass patch

KPK
Central tank battery
Location ID: 450391



Manway leaking



Tank quantity

KPK
Central tank battery
Location ID: 450391



Debris



Debris

KPK
Central tank battery
Location ID: 450391



Staining and debris



Leaking tank and staining

KPK
Central tank battery
Location ID: 450391



Debris



Open bucket with oil

KPK
Central tank battery
Location ID: 450391



Location

Location

KPK
Central tank battery
Location ID: 450391



Thief hatch closed with plyers



Location