

Inspection Photos

API: 017-06632

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 11/17/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. The access road is impassible due to stormwater accumulating along the road. Since the well has been PA'd the road will need to be decompacted, regraded, and reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06632 | Date: 11/17/2025

Inspection Photos



Photo 2. Facing southeast along the access road. There is a metal stand that was left on the roadside.



Inspection Photos




Photo 3. Facing southeast toward the location.



Inspection Photos



Photo 4. Northwest corner of the location facing southeast. It is suspected that there are impacted soils further out from the plugged well.



Inspection Photos



Photo 5. Facing toward southeast side of the location. The excavated impacted material was placed on a piece of plastic with no containment and some of the material has fallen outside of the liner. The pile was removed but it does appear some impacted soil remains in this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06632 | Date: 11/17/2025

Inspection Photos



Photo 6. East side of the location facing southwest. There are blacked stained soils at the east side of the location. This does not appear to be suitable soil for reclamation.

Photo 7. East side of the location facing southwest. There are blacked stained soils at the east side of the location. This does not appear to be suitable soil for reclamation.

