

Interim Reclamation and Stormwater Inspection

November 19, 2025

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 475084

Location Name: LINNEBUR-MANIFOLD/13NWSE

Inspection Document #: 718601193

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name:
LINNEBUR-MANIFOLD/13NWSE
Location ID: 475084




Photo 1. Looking west at the separator shed. Separator opening (red circle).



Photo 2. Appears that nest material/ debris is present in a separator opening.



Inspection Photos
Location Name:
LINNEBUR-MANIFOLD/13NWSE
Location ID: 475084



Photo 3. Looking west across the east side of the location near the evaporation pit. Secondary containment berm around partially buried concrete vessel appears to be compromised and shows signs of stormwater erosion (red circle).



Photo 4. Picture taken looking across the evaporation pit. Stormwater erosion is present in the secondary containment berm near the partially buried vessel. Undesirable weeds such as kochia and russian thistle are present in and around the pit.



Inspection Photos
Location Name:
LINNEBUR-MANIFOLD/13NWSE
Location ID: 475084



Photo 5. Looking east across the north side of the tank battery location. Vegetation on the location is mowed at the time of location. Some desirable perennial vegetation is present in the interim area. Undesirable weeds such as kochia and russian thistle are also present in the interim area.



Photo 6. Looking east across the north side of the tank battery location. See photo 5 comments.



Inspection Photos
Location Name:
LINNEBUR-MANIFOLD/13NWSE
Location ID: 475084



Photo 7. Looking south at the tank battery. Tank battery sign is inadequate.



Photo 8. Fitting on the eastern tank appears to be leaking. Stained soil is present beneath the valve.