

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2025

Submitted Date:

11/21/2025

Document Number:

719700289

FIELD INSPECTION FORM

Loc ID 428139 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428142	WELL	SI	08/01/2025	OW	123-35248	Ball Ranch AC04-72HN	PR

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Wellsite(s): Motor oil; Placards.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	*Refer to Emergency Contact Number section below.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<div style="border: 1px solid black; padding: 5px;"> CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Emergency contact number with Company & Well Name NOT posted at wellsite. Refer to Rule 605.d for guidance. </div>		
Corrective Action:	*Post emergency contact number with Company & Well Name at wellsite. Comply with Rule 605.d. (30-days). See photo(s) #1.		Date: 12/22/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel, pipe.		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellsite(s): 1: Motor oil drum w/ drip containment.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine drives pumpjack. Surrounded by protective shed. Inactive. Shut-down.		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Appears plumbed to surface.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	Inactive.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.609980,-104.427870
Comment:	Centralized Battery serves 1 Location ID (428139). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (481378).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 428142 Type: WELL API Number: 123-35248 Status: SI Insp. Status: PR

Producing Well

Comment: Producing | PR.
Pumpjack Inactive.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>This is a WELL audit. Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (428139). (Well(s): 1: Producing PR). This Location formerly served 1 other well(s). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481378).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700289 and/or Location ID #428139 for PR Well(s) info. B.) Field Audit Report doc. #719700291 and/or Location ID #428139 for PA Well(s) info. C.) Field Audit Report doc. #719700293 and/or Facility ID #481378 for Battery / Facility, Equipment info.</p>	evinsb	11/21/2025
<p>CECMC Audit Report Synopsis:</p> <p>On THU 11/20/2025 at approximately 12:44 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: Ball Ranch/AC03-68HN Pad Location ID: 428139 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>*CORRECTIVE ACTION ITEM(s): 1 1.) Refer to pg 2, "Signs/Marker" section of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	11/21/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700290	Audit photo(s)	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7344328