

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/11/2025

Submitted Date:

11/16/2025

Document Number:

713401113

FIELD INSPECTION FORM

Loc ID 322453 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 17 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210538	WELL	PR	07/01/2025	GW	045-06294	TWIN BUTTES 7101	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-693-6021/911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Unused & damaged secondary containment on location not in use		
Corrective Action:	Comply with CECMC Rule 606		Date: 12/16/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		

Comment:	2 Improperly marked deadman - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		Date:
Corrective Action:			
Type: Bradenhead	# 1		
Comment:	Pressure transducer located on bradenhead, bradenhead valve is accessible		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Open ended piping/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC rule 602		Date: 11/23/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 210538 Type: WELL API Number: 045-06294 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			Insufficient erosion control on lease road
Gravel						Sparse to none
		Culverts				
Ditches						
		Ditches				
Other	Fail					Failure to minimize erosion & sediment
Compaction						

Comment: 1. Failure to minimize erosion & transport of sediment off location/insufficient BMP's
2. Insufficient erosion control on lease road; rill erosion cutting down lease road/insufficient BMP's

Corrective Action: Comply with CECMC rule 1002

Date: 12/01/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 11/11/2025 at approximately 13:50 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP TWIN BUTTES #7101 PAD at Location ID #322453 in Garfield County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Equipment - Open ended piping/wildlife hazard/available for entry by wildlife - Comply with CECMC rule 602 with a CA of 11/23/2025</p> <p>2. Housekeeping - Unused & damaged secondary containment on location - Comply with CECMC rule 606 with a CA of 12/16/2025</p> <p>3. Stormwater - Failure to minimize erosion & transport of sediment off location/insufficient BMP's & Insufficient erosion control on lease road; rill erosion cutting down lease road/insufficient BMP's - Comply with CECMC rule 1002 with a CA of 12/1/2025</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	11/16/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404437863	INSPECTION SUBMITTED	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334039
713401115	713401113 Inspection-Audit Photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334038