

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2025

Submitted Date:

11/21/2025

Document Number:

710500633

**FIELD INSPECTION FORM**

Loc ID 308067 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Waggoner, Kyle		kyle.waggoner@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260920	WELL	PR	11/16/2003	CBM	071-07475	STATE OF COLORADO AR 14-16R	EI
492101	SPILL OR RELEASE	AC			-	State of Colorado AR 14-16R	EG

**General Comment:**

This is an Environmental Inspection for the State of Colorado AR 14-16R well location located in Las Animas County Colorado.

Location ID: 308067  
Well API: 05-071-07475  
Spill ID: 492101

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	1. Well placard located on the meter house. Well placards are illegible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	01/26/2026

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	_____
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	OTHER		
Comment:	Gate on access road is in disrepair, The hinges for the gate are missing allowing the gate to fall and swing upward when unlatched from H-brace to open.		
Corrective Action:	Repair gate and comply with Rule 210 and Rule 602.	Date:	12/22/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 260920 Type: WELL API Number: 071-07475 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 492101 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is an Environmental Inspection for Spill ID 492101. At the time of inspection impacted soils were observed adjacent to the wellhead and throughout the well pad. Impacts to soils shall be remediated in accordance with Rule 912.b. Operator shall collect confirmation samples for Full Table 915-1 contaminants of concern.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500634	Inspection Photos	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7345120">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7345120</a>