

**FORM  
INSP**  
Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/11/2025  
Submitted Date:  
11/17/2025  
Document Number:  
709100598

**FIELD INSPECTION FORM**

Loc ID 317097 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
6 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 31257  
 Name of Operator: FRITZLER RESOURCES INC  
 Address: P O BOX 114  
 City: FORT MORGAN State: CO Zip: 80701

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>
Kyle Waggoner		kyle.waggoner@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Alex Ahmadian		alex.ahmadian@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236210	WELL	PR	08/15/2006	OW	121-08700	JOLLY 2	EI

**General Comment:**  
 On November 11, 2025, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, Alex Ahmadian, and Sienna Madurski inspected the JOLLY-63S55W/18NENE (Location ID 317097) and the Jolly 2 wellhead (API 121-08700).  
 This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

Type			
Comment:	Wellhead signage present		
Corrective Action:		Date:	
Type			
Comment:	Unlabeled blue barrel observed on location.		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.		Date: 11/19/2025

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type			
Comment:	Unused equipment location on site.		
Corrective Action:	Copoly with Rule 606		Date: 02/11/2026

Overall Good:

**Spills:**

Type	Area	Volume		
Comment:	Drips and drabs of hydrocarbons observed around and on the pump jack and around the wellhead.			
Corrective Action:	Cleanup and properly treat or dispose in accordance with Rule 905.e.			Date: 11/20/2025

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 236210 Type: WELL API Number: 121-08700 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404438397	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334600">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334600</a>
709100599	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334597">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334597</a>