

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/11/2025

Submitted Date:

11/17/2025

Document Number:

709100600

FIELD INSPECTION FORM

Loc ID 316950 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Alex Ahmadian		alex.ahmadian@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107600	PIT	AC			-	SWANDA	EI
233402	WELL	PR	04/01/2023	OW	121-05440	SWANDA 1	EI

General Comment:

On November 11, 2025, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, Alex Ahmadian, and Sienna Madurski inspected the SWANDA-63S52W/30NWNW (Location ID 316950), the Swanda 1 wellhead (API 121-05440), and Swanda pit (Facility ID: 107600)

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Location

Overall Good:

Signs/Marker:

Type			
Comment:	Signage present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type			
Comment:	Trash and unused equipment observed on location.		
Corrective Action:	Comply with Rule 606	Date:	11/24/2025

Overall Good:

Spills:

Type	Area	Volume				
Comment:	A pipe connecting frm a partially buried vessel to the exterior of bermed containment was observed.					
Corrective Action:	Operator shall collect confirmation soil samples within area open pipe connecting to the outside of the berm and analyze them for full Table 915-1 analytes to indicate that a historical spill/release has not occurred at this area. Analytical data and plan shall be provided within a Form 19. Operator shall contact EPS Krystal Heibel (krystal.heibel@state.co.us) with any questions.				Date:	11/19/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#				corrective date	
Comment:	A pipe connecting frm a partially buried vessel to the exterior of bermed containment was observed. Multiple open valves observed around wellhead.					
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date:	11/24/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS		
Comment:							
Corrective Action:						Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Burrows observed in berms.				
Corrective Action: Repair or install berms or other secondary containment devices				Date: <u>01/11/2026</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 107600 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 233402 Type: WELL API Number: 121-05440 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Operator is not in compliance with Rule 909.j.(2) for Swanda pit facility. (Facility ID: 107600). Operator has not submitted annual Produced Water Quality Analysis data via a Form 43.

Corrective Action Operator shall submit annual Produced Water Quality Analysis data to the ECMC via a Form 43.

Date: 12/22/2025

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: Operator shall submit an updated Form 15 (Pit Report) that updates the pit's coordinates. Facility coordinates shall be collected on the southeast corner of the pit facility. Pit dimensions shall reflect current pit status on location.

Corrective Action

Date: 12/11/2025

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404438399	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334601
709100601	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7334598