

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2025

Submitted Date:

11/18/2025

Document Number:

716301727

FIELD INSPECTION FORM

Loc ID 334553 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Giussani, Albert	806-894-0200/806-638-1296	albert_giussani@oxy.com	Engineering Advisor
Maestas, Eric	575-420-7825	eric_maestas@oxy.com	
,		dnr_ecmc_engineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211796	WELL	TA	08/29/2025	GW	055-06031	SHEEP MOUNTAIN UNIT 7-9	TA
211828	WELL	SI	10/01/2022	CO2	055-06065	SHEEP MOUNTAIN UNIT 3-4-0	PA

General Comment:

"This is a field audit of the scout card, related documents and the location."
ALL CORRECTIVE ACTIONS FROM PREVIOUS INSPECTION DOC #710500075 THAT HAVE NOT BEEN ADDRESSED ARE STILL ACTIVE AND ACTION IS REQUIRED.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: PHOTO 3: AREA OF IMPACTED SOIL AROUND 3-4-0 WELL.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D

Date: 11/28/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead

2

Comment: IS ACCESSABLE

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 211796 Type: WELL API Number: 055-06031 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: **THIS WELL WAS LAST PRODUCED 10-1-2020, THE WELL WAS DUE FOR AN MIT 10-1-2022, OPERATOR DID NOT PERFORM THE MIT UNTIL 7/14/2025.**

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 211828 Type: WELL API Number: 055-06065 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: **WELL IS PA, IT HAS BEEN OVER 90 DAYS AND THE WELL HAS NOT BEEN CUT AND CAPPED. THERE IS A FORM 5A EXPLAINING THE DELAY FOR THE CUT AND CAP.**

Corrective Action: **CUT AND CAP WELL PER RULE 603.m & 603.n WITHIN 30 DAYS OR CONTACT AREA ENGINEERING STAFF FOR DIRECTIVE. GIVE AREA INSPECTOR tom.beardslee@state.co.us 970-420-3935 AT LEAST 48 HOUR NOTICE BEFORE CUT AND CAP (I WANT TO BE PRESENT FOR THE CUT AND CAP).** Date: 12/18/2025

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 115230 Lat: 37.720241 Long: -105.222924

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: **ONLY 1 PIT PERMIT ON FILE THERE ARE 2 PITS ON LOCTION THERE HAS BEEN 2 FORM 27'S FILED.**

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404440969	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337641
716301728	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337638