

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/18/2025

Document Number:

717000592

**FIELD INSPECTION FORM**

Loc ID 319736 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201184	WELL	SI	01/01/2019	GW	001-06587	BRUCHEZ 3	TA

**General Comment:**

[Routine inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: STORAGE OF SUPL

Comment:

Corrective Action:

Date: 12/19/2025

Overall Good:

**Spills:**

Type	Area	Volume

In Containment:

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type:

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 201184 Type: WELL API Number: 001-06587 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/11/2025 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to ther surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary                      On November 5th 2025 at approximately (11:30 am). I, Inspector Chane Finkenbinder, conducted an on-site inspection.                      Operator: RENEGADE OIL AND GAS                      Location name: BRUCHEZ #3                      API # 001-06587                      Location ID #: 319736                      County: Adams                      While there, I observed TA well.                      During this inspection the following possible compliance issues were observed:                      Rule 606: Weeds, dead weeds, trash, debris &amp; unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment). Corrective Action Date 12/19/2025. See attached photos</p> <p>A follow-up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	11/18/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404441632	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7338485">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7338485</a>
717000593	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7338481">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7338481</a>